

# Errata

## Publication II

In Section III-B, the reason for the frequency shift on the measured results may not be the “air gap between PEN bottom and GND”, but is more likely due to the permittivity used in the simulations ( $\epsilon_r = 3.2$ ). Later measurements resulted in a dielectric constant of  $\epsilon_r = 2.95$ , which was used in [V].