

Goniofluorometer for characterization of fluorescent materials: erratum

Silja Holopainen,^{1,*} Farshid Manoocheri,^{1,2} and Erkki Ikonen^{1,2}

¹Metrology Research Institute, Helsinki University of Technology, P.O. Box 3000, FI-02015 TKK, Finland

²Centre for Metrology and Accreditation, P.O. Box 9, 02151 Espoo, Finland

*Corresponding author: silja.holopainen@tkk.fi

Received 2 December 2008;

posted 2 December 2008 (Doc. ID 104277); published 19 December 2008

The authors wish to correct a calculation error in a figure presented in the original paper. The authors also wish to add an acknowledgement that was not included in the original paper. © 2008 Optical Society of America

OCIS codes: 120.3930, 120.3940, 120.4800, 120.6200.




Fig. 1. Bispectral luminescent radiance factors for three excitation wavelengths measured in 0°/10° geometry.

Due to miscalculation the values in Fig. 6 in [1] are incorrect. A replacement figure with correct values is presented in Fig. 1 of this Erratum.

The authors thank Marko Laurila for his work in characterization of the goniofluorometer and his help in automation of the measurement system related to [1].

Reference

1. S. Holopainen, F. Manoocheri, and E. Ikonen, "Goniofluorometer for characterization of fluorescent materials," *Appl. Opt.* **47**, 835–842 (2008).